Controlling The Same
Inventor's Name: FUJIOKA, et al.
Application No.: New
Docket No.: 107337-00051





FIG.

Controlling The Same
Inventor's Name: FUJIOKA, et al.

Application No.: New Docket No.: 107337-00051



Controlling The Same Inventor's Name: FUJIOKA, et al. Application No.: New Docket No.: 107337-00051

El Com leitro	<u> </u>	8	/	٥	<u>ი</u>	4	2	12
רמונומו	apoin	Data Length	-engrn	Mode	Кеад	Read Latency Count	jount	Keset
ā	PM	DL		MD		RLC		RS

Name	Description
PM	00:16M 01:8M 10:Full Chip 11:0M(Def.)
DL	00 :8word burst 01 :16word burst 10 :32word burst 11 :Continuous burst
MD	0 :Synchronous Burst Enabled 1 :Asynchronous Page Enabled(Def.)
RLC	000 :Latency Count=2 001 :Latency Count=3 010 :Latency Count=4 011 :Latency Count=5
RS	0 :Reset Enabled(Def.) 1 :Reset Disabled

Controlling The Same Inventor's Name: FUJIOKA, et al. Application No.: New Docket No.: 107337-00051

MODE	CE2	/CE1	30/	/WE	/ADS	/LB	/UB	DQ ₀₋₇	DQ ₈₋₁₅	Retention
Power Down/Reset	L	Н	×	×	×	×	×	HiZ	HiZ	No/Partial
Standby	Н	Н	×	×	×	×	×	HiZ	HiZ	Yes
Output Disable	н	L	Н	Н	×	×	×	HiZ	HiZ	Yes
Read	Н	7	7	I	×		٢	Dout	Dout	Yes
No Read	Н	7	٦	I	×	Ξ	Ξ	HiZ	HiZ	Yes
Lower Byte Read	Ι	L	٦	π	×		Ŧ	Dout	HiZ	Yes
Upper Byte Read	н	Γ	٦	I	×	エ		ZIH	Dout	Yes
Write	Н	L	×	Γ	×			Din	Din	Yes
Abort Write	Ι	Γ	X	Γ	×	Ι	Ξ	Invalid	Invalid	Yes
Lower Byte Write	Н	J	×	٦	×	٦	I	Din	Invalid	Yes
Upper Byte Write	H	L	X	7	×	I	ب	Invalid	Din	Yes
Illegal	н	٦	Γ	٦	×	×	×		-	

Controlling The Same Inventor's Name: FUJIOKA, et al.

Application No.: New Docket No.: 107337-00051

CODE 6th MSB 5th MSB 4th MSB MSB 3rd 3rd WR MSB 2nd WR MSB 1st 1st MSB BD sednence CMD ADD

FIG. 5A